

Quantum 4 Manual



Quantum 4-665

X 600 mm
Y 600 mm
Z 500 mm

Quantum 4-6105

X 600 mm
Y 1000 mm
Z 500 mm

Quantum 4-8105

X 800 mm
Y 1000 mm
Z 500 mm

(other sizes on application)


Quantum 4 Manual CMMs are supplied with:-

- Inspect³D Measuring Software
- Dell Computer
- Colour Printer
- Desk
- Calibration Sphere
- Renishaw TP8 Probe
- Installation & Calibration
- 2 day Manual CMM Training Course at QCT
- 1 Year Warranty



Optional Software Modules

- Inspect²CAD
IGES based CAD inspection software including one day training course plus updates and technical support for 6 months.



Optional Probe Upgrade

- Renishaw MH20i
Manual probe head (in lieu of TP8)

Upgrade

Manual to CNC
Upgrade Kit
(fitting costs to be advised)

Optional Extras

- Fine Feed Controls
- Active Temperature Compensation System

**QCT Quantum 4
Manual Co-ordinate
Measuring Machines**